Jeff Welch Colonial Roofing, Inc. 8/12/2022 | 36 Photos



Kensington Preserve 1714

Section 1

Tile repair of cracked/broken, and skid tile and gutter cleaning before and after photos.



Project: Kensington Preserve Date: 4/11/2022, 8:23am Creator: Jeff Welch





Project: Kensington Preserve Date: 6/7/2022, 10:35am Creator: Antonio Chrisman

3



4



Project: Kensington Preserve Date: 6/7/2022, 10:38am Creator: Antonio Chrisman

Project: Kensington Preserve Date: 6/7/2022, 10:43am Creator: Antonio Chrisman















