

Jeff Welch

Colonial Roofing, Inc.

8/12/2022 | 12 Photos



# Kensington Preserve 1730

# Section 1

Photos of cracked/ broken roof tile before and after.

1




Project: Kensington Preserve  
Date: 6/8/2022, 11:26am  
Creator: Antonio Chrisman

2



Project: Kensington Preserve  
Date: 6/8/2022, 11:26am  
Creator: Antonio Chrisman

3



Project: Kensington Preserve  
Date: 6/8/2022, 11:28am  
Creator: Antonio Chrisman


4




Project: Kensington Preserve  
Date: 6/8/2022, 11:29am  
Creator: Antonio Chrisman




Project: Kensington Preserve  
Date: 6/8/2022, 11:32am  
Creator: Antonio Chrisman



Project: Kensington Preserve  
Date: 6/8/2022, 11:33am  
Creator: Antonio Chrisman




Project: Kensington Preserve  
Date: 6/8/2022, 11:33am  
Creator: Antonio Chrisman




Project: Kensington Preserve  
Date: 6/8/2022, 12:34pm  
Creator: Antonio Chrisman




Project: Kensington Preserve  
Date: 6/8/2022, 12:37pm  
Creator: Antonio Chrisman



Project: Kensington Preserve  
Date: 6/8/2022, 12:39pm  
Creator: Antonio Chrisman



Project: Kensington Preserve  
Date: 6/8/2022, 12:40pm  
Creator: Antonio Chrisman



Project: Kensington Preserve  
Date: 6/8/2022, 12:48pm  
Creator: Antonio Chrisman