

Jeff Welch

Colonial Roofing, Inc.

8/12/2022 | 19 Photos



Kensington Preserve 1722

Section 1

Tile repairs for cracked/broken roof tile and slide tile before and after.

1



Project: Kensington Preserve
Date: 6/7/2022, 1:58pm
Creator: Antonio Chrisman

2



Project: Kensington Preserve
Date: 6/7/2022, 2:01pm
Creator: Antonio Chrisman

3



Project: Kensington Preserve
Date: 6/7/2022, 2:02pm
Creator: Antonio Chrisman


4



Project: Kensington Preserve
Date: 6/7/2022, 2:03pm
Creator: Antonio Chrisman




Project: Kensington Preserve
Date: 6/7/2022, 2:09pm
Creator: Antonio Chrisman



Project: Kensington Preserve
Date: 6/8/2022, 8:42am
Creator: Antonio Chrisman




Project: Kensington Preserve
Date: 6/8/2022, 8:43am
Creator: Antonio Chrisman




Project: Kensington Preserve
Date: 6/8/2022, 8:47am
Creator: Antonio Chrisman




Project: Kensington Preserve
Date: 6/8/2022, 9:00am
Creator: Antonio Chrisman



Project: Kensington Preserve
Date: 6/8/2022, 9:02am
Creator: Antonio Chrisman



Project: Kensington Preserve
Date: 6/8/2022, 9:03am
Creator: Antonio Chrisman



Project: Kensington Preserve
Date: 6/8/2022, 9:19am
Creator: Antonio Chrisman

13



Project: Kensington Preserve
Date: 6/8/2022, 9:30am
Creator: Antonio Chrisman

14



Project: Kensington Preserve
Date: 6/8/2022, 9:51am
Creator: Antonio Chrisman

15



Project: Kensington Preserve
Date: 6/8/2022, 10:09am
Creator: Antonio Chrisman

16



Project: Kensington Preserve
Date: 6/8/2022, 10:26am
Creator: Antonio Chrisman

17



Project: Kensington Preserve
Date: 6/8/2022, 10:51am
Creator: Antonio Chrisman

18



Project: Kensington Preserve
Date: 6/8/2022, 10:52am
Creator: Antonio Chrisman

19



Project: Kensington Preserve
Date: 6/8/2022, 10:53am
Creator: Antonio Chrisman