

Jeff Welch

Colonial Roofing, Inc.

8/12/2022 | 12 Photos



Kensington Preserve 1734

Section 1

Before and after photos of repaired cracked/broken roof tile.

1



Project: Kensington Preserve
Date: 6/8/2022, 12:54pm
Creator: Antonio Chrisman

2



Project: Kensington Preserve
Date: 6/8/2022, 1:20pm
Creator: Antonio Chrisman

3



Project: Kensington Preserve
Date: 6/8/2022, 1:20pm
Creator: Antonio Chrisman

4



Project: Kensington Preserve
Date: 6/8/2022, 1:27pm
Creator: Antonio Chrisman

5



Project: Kensington Preserve
Date: 6/8/2022, 1:28pm
Creator: Antonio Chrisman

6




Project: Kensington Preserve
Date: 6/8/2022, 1:28pm
Creator: Antonio Chrisman

7



Project: Kensington Preserve
Date: 6/8/2022, 1:43pm
Creator: Antonio Chrisman


8




Project: Kensington Preserve
Date: 6/8/2022, 1:47pm
Creator: Antonio Chrisman



Project: Kensington Preserve
Date: 6/8/2022, 1:48pm
Creator: Antonio Chrisman



Project: Kensington Preserve
Date: 6/8/2022, 1:49pm
Creator: Antonio Chrisman



Project: Kensington Preserve
Date: 6/8/2022, 2:03pm
Creator: Antonio Chrisman



Project: Kensington Preserve
Date: 6/8/2022, 2:09pm
Creator: Antonio Chrisman